


[1]

VELOCITY SERIES HARNESSES 1 Break-Away Lanyard Keepers



1 Break-Away Lanyard Keepers Lanyard keepers reduce the risk of dragging and snagging lanyards. The

keeper is on the chest to make the lanyard end more accessible.




2 Finished Webbing Ends

Keeps the webbing ends from fraying or getting damaged as well as providing a clean and professional look.



3 Identification

Now your employees can personalize their harnesses without jeopardizing the integrity of the webbing.



4 Webbing Wear Indicator

Unique red webbing core provides a visual warning to the user that the webbing has been damaged and should be taken out of service.

			Velocity HUV		Velocity w/ 3 D-rinas		
Size	Chest	Legs	Part#			Weight	100
S - L	Pass-Thru	Pass-Thru	01700	2.75	01702	3.00	1
XL - 2XL	Pass-Thru	Pass-Thru	01701	3.00	N/A 🛛 📕	N/A	
S - L	Pass-Thru	Tongue Buckle	01703	2.75	01705 🌘	3.00	ALL ALL ALL
XL - 2XL	Pass-Thru	Tongue Buckle	01704	3.00	01706	3.50	

Your employees and customers will appreciate this higher quality economy harness for an incredible value. While other manufacturers look to cut costs by cheapening up their lower end products, Guardian Fall Protection proves that we will not sacrifice quality or the protection of your employees to save a few nickels and dimes.

The new Velocity Harness by Guardian Fall Protection brings the best economy harness to the market. Our engineers revamped the tired old basic harness into a higher quality product that your employees and customers will enjoy.

The Service Warehouse (800) 822-6004

Dual Lanyard Keepers: Other manufacturers provide only one or none on their economy harness.

Finished Webbing Ends: Keeps the webbing ends from getting damaged as well as providing a clean and professional look.

Identification: Now your employees can personalize their harnesses without jeopardizing the integrity of the webbing.

Webbing Wear Indicator: The only economy harness on the market that provides a visual warning to the user and safety director that the webbing has been damaged and should be taken out of service.

[4]